

## **Inspection Report 30<sup>th</sup> October 2012**

### **John Grose Group Ltd, Unit E, Foxtail Road, Ransomes Europark, Ipswich, IP3 9RT** **LB met with John Forder**

As mentioned in the inspection notes of 24/9/10, the existing permit contained errors. The process description and site plan have changed due to the introduction of 3 new spray booths in 2004. [Maxon TA600 3000x2000].

#### *Condition 2*

Filter specification for TD500 Dust Extraction System not available.

#### *Condition 4*

VOC inventory Jan-Oct 2012 viewed – remains under 2 tonne year to date.

#### *Condition 5*

Paul Forder confirmed that the company as a whole constantly strives to use the most up to date techniques available to reduce emissions.

#### *Condition 6*

Daily and monthly visual check records inspected

#### *Condition 7*

Thorough maintenance programme in place. David Utting Engineering used to maintain all booth and dust extraction systems. Filters changed every 6 months. David Utting on 24hr call out if needed.

#### *Condition 9 & 14*

Should adverse results occur, plant will be shut down until repair complete. 3 booths so process other 2 can be used if one fails.

#### *Condition 13*

No odour noticeable on or off site

#### *Condition 20 & 21*

Gauges fitted to all booths which are under negative pressure

#### *Condition 24-34*

VOC control techniques satisfactory and there was a high standard of housekeeping. Most up to date techniques used. Waste taken by AWS Waste Mngt on request.

#### *Condition 35–37*

Stacks viewed ok, waiting for confirmation of velocity.

Louise Burns