

visit made. met site owners. premises uses bp oil and shop is a londis franchise. they are still below the annual throughput for VR2. They have an annual contract with gilbarco. last annual test was carried out on 25.02.10 and a new one is scheduled in. Asked site owner to send me the new report after gilbarco carry out the checks. checked the inspection of the PRV and VR system by gilbarco. test done 31.03.09. it is a 3 year test with the next one due in 2012. checked the signage on the petrol tank connection points and the VR point. all present although slightly smeared with mud. the caps are padlocked and all deliveries are driver assisted with site owner watching over. the seal in 2 caps were in need of replacement and this was pointed out to the owner. he advised that these would be replaced by gilbarco.