

Ofton Motors Westbourne Road

EP/000000012

Inspection Date 23/02/2011

1. No changes to process.
2. Only oil produced on premises being burned.
3. No incidents, no smoke beyond 10 minutes after lighting from cold.
4. Serviced yearly.
5. Instructions on wall beside burner.
6. Stack correct.
7. Clean up materials.
8. Use limited to the two owners.

Low risk, compliant with permit.