

Donalds Garage Ipswich Ltd



15/11/12 LB

Inspection Report – met with Mr David Sample, Manager

Thermobile SBSH60 WOB has been installed for just over a year.

Waste oil is collected from the vehicles using a waste oil drainer. It is then sucked up a workpipe to a collection tank in the oil store. All enclosed – no need to openly pour oil into tank.



Conditions 1,2, 7

Only oil from own arising is used as all enclosed system so difficult to add other substances.

Conditions 4,5

Emissions to air are always clear, operator never seen dark smoke from chimney.

Condition 6

Should emissions occur, WOB will be shut down and engineer called.

Condition 8,9,10,11

It has not been necessary to clean WOB out yet but it will be maintained and serviced in accordance with manufacturer's instructions.

Conditions 12,13

Stack approx. 7 metres high – acceptable due to low emissions, No cowl or cap.

Conditions 14,15

Staff have all been trained, new starters would not operate WOB until trained. Spillage kit attached to side of oil tank.