



Vapour Recovery Inspection & Test Certificate

Test Details

Site Name	ASDA IPSWICH.				
Site Address	GODDARD ROAD, IPSWICH.				
Oil Company	ASDA	Inspected By	R.WASTIE.		
Date of Test	20/04/2012	Certificate No	120420UKRW	Test Kit No	200050

Stage 1B Test Results

	PASS / FAIL/N/A		YES, NO, N/A
System Integrity	PASS	Type of Manifold (High, low, Underground)	LOW
P&V Valve Pressure Test	PASS	Clean Flame Arrestor	YES
P&V Valve Vacuum Test	PASS	System Drain Down	N/A
P&V Valve Leak Test	PASS	Petrol Tank Numbers	2.3
Numbers of P&V Valves	1	Diesel Tank Numbers	1.4
New P&V Valves Fitted	NO	Diesel Vents in Manifold	NO
Caps, Seal & Signage	PASS	If Applicable Which Tank	N/A

Overfill Valve Leakproof Results

Tank No		PASS / FAIL
Tank 1		
Tank 2		✘
Tank 3		✘
Tank 4		
Tank 5		
Tank 6		
Tank 7		
Tank 8		
Tank 9		

Stage 2 Test Results

	PASS/FAIL/ NA
Stage 2 Return Line	

Stage 2 Air to Product Ratio Test Results

Pump No	Product	Air to Product Ratio %	PASS / FAIL

See following sheet for more information

