

Risk Assessment for Petrol Stations

Site	Meredith Service Station, 554 Norwich Road, Ipswich, Suffolk, IP1 6JR
Process carried out	Unloading of petrol
Date	15.12.11

	Yes	No	N/A	Score	Comments
Table A: Compliance					
(a) Incident leading to justified complaint but no breach of any permit condition	0	0	0	0	
(b) Incident leading to a justified complaint	5 per incident	0	0	0	
(c) Breach of permit not leading to formal action	10 per incident	0	0	0	
(d) Incident leading to formal caution, Enforcement Notice or prosecution	15 per incident	0	0	0	
(e) Incident leading to a Prohibition Notice or Suspension Notice	20 per incident	0	0	0	
Table B: Monitoring, maintenance and records					
(a) Are emissions monitored as required in the permit? Are emissions and emissions monitoring recorded as required in the permit?	0	10	0	0	
(b) Process operation modified where any problems indicated by monitoring?	0	5	0	0	
(c) Fully documented and adhered to maintenance/service plan in line with permit? Has a written maintenance programme been provided to the regulator with respect to pollution control equipment?	0	5	0	5	
(d) Full documented records as required in permit available on-site? Is there a log book at the authorised premises incorporating details of all maintenance, examination and testing, inventory checking, installation and repair work carried out?	0	5	0	5	no VR certificate in
(e) All relevant documents forwarded to the authority by the date required?	-5	10	0	10	no date was set by
Table C: Management, Training, Responsibility					

(a) Are procedures in place to ensure proper management, supervision and training for process operations, proper use of equipment and effective preventative maintenance on all plant and equipment concerned with the control of emissions to the air?	0	5	0	5	
(b) Are all staff aware of their responsibilities under the permit?	0	5	0	0	
(c) Does the operator maintain, and make available on request, a statement of training requirements for each operational post?	0	5	0	0	This was not check
(d) Does the operator keep and make available a record of the training received by each person whose actions may have an impact on the environment?	0	5	0	0	This was not check
Is there a competent trained person who remains near the tanker during unloading? (delivery drivers may be trained as the competent person)	0	5	0	0	
(f) Is an 'appropriate' environmental management system in place and working effectively?	-5	0	0	0	
Overall Score				25	
Category (<30pts:low, 30-55pts:medium, >55pts:high)				LOW	

in logboo

out a reminder letter had to be sent out. No response to say that action taken regarding sig

oked during my visi

oked during my visi

image and no response regarding details confirmator