Our ref: WK/201105617

Please ask for: Varuna Addy

Direct Dial: 01473 433117

Email: varuna.addy@ipswich.gov.uk



Grafton House 15-17 Russell Road Ipswich Suffolk IP1 2DE

www.ipswich.gov.uk

Mrs Debbie Wood Morrisons Petrol Filling Station Boss Hall Road Ipswich Suffolk IP1 5BN

9th September 2011

Dear Mrs Wood,

The Pollution Prevention and Control Act 1999 The Environmental Permitting (England and Wales) Regulations 2010 Inspection of petrol station

Thank you for your assistance during my visit at the petrol station. This visit was undertaken to check for compliance with Permit reference PS4/VPA/12/09.

I found that compliance with the Permit conditions were satisfactory at the time of my visit. I have made reference to the conditions where improvements could be made/ information is requested below:

Condition 2: As discussed, I should be grateful if you could provide a copy of the most recent inspection by Eurotank for our own records.

Condition 9: Two of the rubber seals on the connection points may need replacing and you advised me that you would be reporting this to the service engineers. A third seal on a disused petrol connection point was damaged. I noted that there was no indication that the connection point was disused. You may wish to put a sign on/near that connection point to notify tanker drivers and avoid fuel being unloaded in error via that point.

Condition 13: It is a legal requirement that signs stating "Connect vapour return line before off-loading" or similar working and a sign referring to the maximum number of tanks that can be unloaded simultaneously is placed adjacent to the vapour return point. I would recommend that the signs are regularly cleaned to ensure that drivers are able to follow the instructions.

Yours sincerely,

Varuna Addy Acting Principal Environmental Health Officer Environmental Health Cc: The Store Manager Morrisons Supermarket Boss Hall Road Ipswich Suffolk IP1 5BN