

Pls scan to EPI — 19
'Info recd'
3rd year vapour recovery
inspection

FROM:

ROUNDWOOD SERVICE STATION,
436, Woodbridge Road,
Ipswich,
IP4 4EN.



TO:

Mrs . Varuna Addy,
Senior Environmental Health Assistant,
Environment Protection Services,
Ipswich Borough Council,
Grafton House,
15-17, Russell Road,
Ipswich, IP1 2DE.

Dear madam,

14th Apr'2011.

RE : VAPOUR RECOVERY INSPECTION – 3RD YEAR.

As I promised you, Here, I am glad to inform you that we have finish our above inspection on 21st of Mar'2011.

Find attached documents.

I hope our documents shall be given evidence as your required.

I remain,

Yours truly,


.....

Elango,

Manager.

V & S SERVICE
436 WOODBRIDGE ROAD
IPSWICH IP4 4EN
Tel: 01473 715198
VAT No. 770 2078 42



GILBARCO
VEEDER-ROOT

CLEARANCE CERTIFICATE / JOB REPORT / WORK SHEET

017

SITE NAME & ADDRESS Dennywood Street Woodside Road Milton		DESCRIPTION OF WORK 3rd year vapor recovery inspection	
JOB NO.: 24664	ENGINEER: M. L. G. 24	TRAVEL HOURS	SITE HOURS
ENGINEER: NAME(S) M. L. G. 24			
No OF WORKERS 1			
ARE ISOLATION PROCEDURES REQUIRED? (Tick Box) (If YES site must be aware of the procedure)		YES	NO
			<input checked="" type="checkbox"/>

STEPS	HAZARDS	RISKS HIGH/MED/LOW	HOW TO REDUCE OR ELIMINATE RISKS	REMAINING RISK
	working on electrical cables with gas released by pump	M	check power (Heres) for circuit close of car wash close of pump tank	

*** A NEW CLEARANCE CERTIFICATE IS REQUIRED EACH DAY OF DOING JOB - UPDATE IF ADDITIONAL HAZARDS OR CIRCUMSTANCES CHANGE ***

BEFORE WORK COMMENCES

As the Contractor I confirm that I will carry out work as agreed.

Signed: *[Signature]* Date: 21/3/11

On behalf of the site, I have reviewed and agree to these work arrangements.

Signed: *[Signature]* Date: 21/3/11

WORK COMPLETED SAFELY

Retailer Signed: *[Signature]* Date: 21/3/11

Print Name: L. G. 24

Comments: DONE.

- CHECK LIST (Circle as required)**
- Clearance Certificate fully completed YES / NO
 - Safety Method Statement available (Medium Risk only) YES / NO
 - Pre Accreditation Certification Available (High Risk Only) YES / NO / N/A
 - Have you shown the site your Safety Method Statement YES / NO
 - Certificate signed by Contractor/Retailer YES / NO
 - All obvious hazards identified and precautions taken YES / NO
 - Did a near miss occur whilst on site YES / NO

NOTICE TO CUSTOMER:-
LABOUR AND MATERIALS SHOWN WILL BE CHARGED TO THIS JOB.

Our ref: EP/000000019
Your ref: 1.2/SR/5/06
Please ask for: Mrs Varuna Addy
Direct Dial: 433117
Email: varuna.addy@ipswich.gov.uk



IPSWICH
BOROUGH COUNCIL

Messrs Sritharan & VaSeeharan
Roundwood Service Station
436 Woodbridge Road
Ipswich
IP4 4EN

Grafton House
15-17 Russell Road
Ipswich Suffolk
IP1 2DE

www.ipswich.gov.uk

20 January 2011

Dear Messrs Sritharan & VaSeeharan,

The Pollution Prevention and Control Act 1999
Environmental Permitting (England and Wales) Regulations 2010
Roundwood Service Station

In accordance with the requirements of the above legislation, I am required to carry out an inspection of Roundwood Service Station in order to establish compliance with Environmental Permit (reference: 1.2/SR/5/06).

I intend to carry out a visit on the 21 February 2011 at 10am. Please contact me if the proposed date and time are not convenient. If I do not hear from you, I will assume that this is convenient.

Please contact me if you have any queries.

Yours sincerely,

A handwritten signature in black ink, appearing to be 'V. Addy'.

Mrs Varuna Addy
Senior Environmental Health Assistant
Environmental Protection Services