

NORTHERN PUMP DISTRIBUTORS

TEL: 01924 275318 FAX: 01924 271594

VAPOUR RECOVERY STAGE 1B MAINTENANCE CHECKLIST

Site Details	3) Maintenar	Maintenance Schedule		
Name: Snow Ipswish 1-821		All drained off – Yes		
Address: Eleubrook Road, Epsysich, Suffolk, IP1 9RP		No	. 1	
Address: Elikasiss A Rossa		If 'no', state why		
E PANICK.		Product removed - Yes		
Juttolky		No		
IPZ SKP.	*****	If 'yes', how much		
	Vent Caps:	Visual inspection (cle	an up if required)	
Tel No: 014743 688326.		Good condition		
		Poor condition		
Oil Company Name: 3-C.	(Any recomm	nendations in comments box	below)	
	Collection Pr	oints: Visual inspection (cle		
Date of Last Maintenance Visit:		Good condition		
<u> </u>	14	Poor condition		
equency of Visits:	(Any recomm	nendations in comments box	below)	
2) About The System - tick as appropriate	ITEM	P/ON V/ON DURATION	P/OFF V/OFF PASS	
			/FAIL	
Manifold:	PV Cap 1		1000	
	PV Cap 2			
	PV Cap 3			
111	PV Cap 4			
U/ground Covered	Collect			
	Collect 2			
	Collect 3 Collect 4		-	
Other (please specify)				
Other (please specify)				
Collection Point:	Check / repa	air / clean / replace the following	ina items	
Above Ground	- tick on com	pletion		
Dalan Connect	Warning sign	ns		
Below Ground	Pipe clips		¥	
0	Collection du	ust cap		
Drain Point:	Dust cap par			
	Overfill prevenue	ention valves		
	····· Anti-cross co	ontamination valves	~	
	Clean & emr	oty manholes of water if requi	rad	
	I eak detection		146	
Back Into A Tank	LOGIN GOTGOTI	on ayatem	111	
Underground Pipework Is:		urther Comments:		
	- 1x J.R	Come + Lock -		
Other (please specify)		DETECTION NOT	AVAILABLE,	
Multiple Collection Points:	_			
	/			
	Signature fr	om site manager or other	competent	
If 'yes', how many	completion	on one manager or other	competent person, on	
North and All Control	- ()			
Number of Vent Caps	Z. Print: K	HBM		
Vent Stack:				
Against a Wall	Sign:			
	-			
Freestanding	Date: 1.6	-10-11		
Checklist Performed By:		1		
,			//	
Print: /() ARKICK Sign:	10-2	Date: (/	10/4	
			1	