

Risk Assessment for Petrol Stations

Site	elstead Service Station, Ellenbrook Road, Ipswich, Suffo
Process carried out	Unloading of petrol
Date	15.12.11

	Yes	No	N/A	Score	Comments
Table A: Compliance					
(a) Incident leading to justified complaint but no breach of any permit condition	0	0		0	
(b) Incident leading to a justified complaint	5 per incident	0		0	
(c) Breach of permit not leading to formal action	10 per incident	0		0	
(d) Incident leading to formal caution, Enforcement Notice or prosecution	15 per incident	0		0	
(e) Incident leading to a Prohibition Notice or Suspension Notice	20 per incident	0		0	
Table B: Monitoring, maintenance and records					
(a) Are emissions monitored as required in the permit? Are emissions and emissions monitoring recorded as required in the permit?	0	10	0	0	
(b) Process operation modified where any problems indicated by monitoring?	0	5	0	0	
(c) Fully documented and adhered to maintenance/service plan in line with permit? Has a written maintenance programme been provided to the regulator with respect to pollution control equipment?	0	5	0	5	this was not seen c
(d) Full documented records as required in permit available on-site? Is there a log book at the authorised premises incorporating details of all maintenance, examination and testing, inventory checking, installation and repair work carried out?	0	5	0	5	this was not seen c
(e) All relevant documents forwarded to the authority by the date required?	-5	10	0	0	
Table C: Management, Training, Responsibility					

(a) Are procedures in place to ensure proper management, supervision and training for process operations, proper use of equipment and effective preventative maintenance on all plant and equipment concerned with the control of emissions to the air?	0	5	0	5	The site manager \
(b) Are all staff aware of their responsibilities under the permit?	0	5	0	5	The site manager \
(c) Does the operator maintain, and make available on request, a statement of training requirements for each operational post?	0	5	0	5	The site manager \
(d) Does the operator keep and make available a record of the training received by each person whose actions may have an impact on the environment?	0	5	0	0	This was not check
Is there a competent trained person who remains near the tanker during unloading? (delivery drivers may be trained as the competent person)	0	5	0	0	
(f) Is an 'appropriate' environmental management system in place and working effectively?	-5	0	0	0	
Overall Score				25	
Category (<30pts:low, 30-55pts:medium, >55pts:high)				LOW	

on site at the time of the inspection although the Health and Safety compliance manager I

on site at the time of the inspection although the Health and Safety compliance manager I

· was unaware during my visit. The Health and Safety manager has advised that training wi

· was unaware during my visit. The Health and Safety manager has advised that training wi

· was unaware during my visit. The Health and Safety manager has advised that training wi

cked during my visit. However, the Health and Safety manager advises that training is unde

has arranged for this to be sorted out. No visit has been undertaken by IBC to check wheth

has arranged for this to be sorted out. No visit has been undertaken by IBC to check wheth

ll be provided again but no visit by IBC to determine whether this has been completec

ll be provided again but no visit by IBC to determine whether this has been completec

ll be provided again but no visit by IBC to determine whether this has been completec

ertaken and recorded

ier measures now put in place

ier measures now put in place